

1623Z 12 APR 64

SECRET

TO : DIRECTOR

FROM : [REDACTED]

ACTION:

INFO :

OPS 1-8

TOR: 1747Z 12 APR 64

PRIORITY

IN 72936

CITE

0537

1. ON MSN S184A BW SENSOR FOR RPM FAILED AND POSS SENSOR FOR AC GEN. AM ADVISED WE HAVE NO SPARE SENSORS FOR THE [REDACTED]

2. PLS ADVISE CURRENT STATUS OF SPARE SENSORS AND SUGGEST AVAIL SPARES ACCOMPANY [REDACTED] PARTICULARLY TACHOMETER TRANSDUCER SP 69178 (GFE PART).

END OF MESSAGE

SECRET